

Summary Report of Hazardous Waste and Sewage Spill Incidents per Water Code Section 13271

I. Petroleum Products

Date Reported*	Date Discovered	Discharger	Location	Problem	Action
3/6/03	3/6/03	CARDLOCK FUELS	1431 RAYMOND, N., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: DIESEL CONTAMINATED SOIL	LEAK BEING CONFIRMED
3/10/03	3/10/03	MICHELSON WATER RECLAMATION PLANT	3512 MICHELSON DR., IRVINE	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
3/17/03	1/21/02	FORMER UNOCAL STATION #5002	1210 EUCLID AVENUE S, LA HABRA	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
3/18/03	3/10/03	PENSKE TRUCK LEASING	620 BALL ROAD, EAST, ANAHEIM	UNDERGROUND STORAGE TANK LEAK: DIESEL CONTAMINATED SOIL	SITE WORKPLAN UNDERWAY
3/20/03	3/12/03	WEST SAN BERNARDINO COUNTY WATER DISTRICT	855 BASELINE WEST, RIALTO	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	POLLUTION CHARACTERIZATION
3/20/03	3/20/03	SHELL SERVICE STATION	1600 VALLEY BOULEVARD WEST, COLTON	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	POLLUTION CHARACTERIZATION
3/25/03	1/6/03	SHELL	230 LINCOLN AVENUE, CORONA	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	SITE WORKPLAN UNDERWAY
3/27/03	3/27/03	SHELL SERVICE STATION	12301 HEACOCK STREET, MORENO VALLEY	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
3/27/03	3/27/03	SHELL OIL PRODUCTS US	201 STATE COLLEGE BLVD., S., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	SITE WORKPLAN UNDERWAY
4/2/03	4/2/03	SHELL OIL PRODUCTS US	2331 KATELLA AVE., E., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: BENZENE CONTAMINATED SOIL	SITE WORKPLAN UNDERWAY
4/3/03	4/3/03	SHELL SERVICE STATION	490 EAST SAN JACINTO AVENUE, PERRIS	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
4/3/03	3/21/03	REDLANDS SHELL	127 REDLANDS BOULEVARD EAST, REDLANDS	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	POLLUTION CHARACTERIZATION
4/9/03	3/28/03	SETCO	4875 HUNTER, E., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
4/24/03	4/22/03	ORANGE COUNTY TRANSPORTATION AUTHORITY	1717 VIA BURTON ST., E., ANAHEIM	UNDERGROUND STORAGE TANK LEAK: CONTAMINATED SOIL	SITE WORKPLAN UNDERWAY

I. Petroleum Products

Date Reported*	Date Discovered	Discharger	Location	Problem	Action
4/29/03	4/24/03	FOSS BROTHERS DIARY	6641 RIVERSIDE DRIVE, CHINO	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	SITE WORKPLAN SUBMITTED
5/16/03	4/9/03	FORMER SHELL STATION	859 MOUNTAIN AVENUE NORTH, ONTARIO	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	POLLUTION CHARACTERIZATION
5/19/03	5/15/03	SHELL STATION	1600 JAMBOREE, NEWPORT BEACH	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	LEAK BEING CONFIRMED
5/27/03	5/27/03	SHELL SERVICE STATION	1850 HAMNER AVENUE, NORCO	UNDERGROUND STORAGE TANK LEAK: GASOLINE CONTAMINATED SOIL	SITE WORKPLAN SUBMITTED

Report date is the date on the Unauthorized Release Report which is filled out by the local agency or the discharger. This report may not contain an accurate listing of all the new cases due to the ongoing reconciliation between the Geotracker/GEIMS, DOD, and Local Agency databases.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
4/23/03	4/22/03	35203	Private Property Owner	10372 Mira Vista Drive, Tustin, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a private lateral due to unknown blockage. None of the spill was recovered, but it was contained on the private property's land where it percolated. The blockage was relieved, and the affected area was cleaned up by a private contractor with the assistance of OCSD's staff.
4/28/03	4/28/03	35606	City of Orange	718 N Harington & Nicolas, Orange, Orange County	SSO	700	An estimated 700 gallons of sewage overflowed from a manhole due to grease blockage. Approximately 450 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest of the spill discharged into a nearby storm drain. The blockage was cleared and the affected area was cleaned up by City of Orange staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/1/03	5/1/03	35366	City of Huntington Beach	6905 Warner Blvd, Huntington Beach, Orange County	SSO	900	An estimated 900 gallons of sewage overflowed from a manhole due to grease blockage. All 900 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was cleared, the affected area was cleaned up and disinfected by City of Huntington Beach staff.
5/3/03	5/3/03	35365	Private Property Owner	Hermosa & Foothill, Rancho Cucamonga, San Bernardino County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a private lateral due to grease blockage. Approximately 400 gallons of the spill were contained and returned to the operational sewer system, while the rest discharged into a nearby storm drain. The blockage was cleared and the affected area was cleaned up by private property contractor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/5/03	5/5/03	35604	EMWD	Thoroughbred Ln, Moreno Valley, Riverside County	SSO	2,640	An estimated 2,640 gallons of sewage overflowed from a manhole due to grease blockage. Approximately 300 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest discharged into a nearby storm drain. The blockage was cleared and the affected area was cleaned up by EMWD staff.
5/5/03	5/5/03	35605	EMWD	Patterson Ave & Simpson Road, Winchester, Riverside County	TRW	500,000	An estimated 500,000 gallons of tertiary recycled water was released from a broken valve. All 500,000 gallons of the water flowed into farmland nearby the Winchester ponds where it percolated. The valve was repaired and the affected area was cleaned up by EMWD staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/6/03	5/6/03	35363	Private Property Owner	700 N Brookhurst St, Anaheim, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private lateral due to paper blockage. Approximately 50 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest discharged into a nearby storm drain. The blockage was cleared and the affected area was cleaned up by private property contractor.
5/11/03	5/11/03	35745	EVWD	Between Langstaff Street and Pottery Street, Elsinore, Riverside County	SSO	4,100	An estimated 4,100 gallons of sewage overflowed from a manhole due to blockage caused by vandalism. Vandals pushed debris and a few 1"W x 12"L wooden sticks into a manhole. 400 gallons of the spill were contained, recovered, and returned to the operational sewer system. 3,700 gallons of the spill were not recovered and were discharged into a local storm drain and on to the storm drain channel where it percolated. The blockage was relieved; the affected area was cleaned up, and disinfected by EVWD.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/12/03	5/12/03	35603	City of La Habra	Beach Blvd & Lambert Rd, La Habra, Orange County	SSO	2,000	An estimated 2,000 gallons of sewage overflowed from a manhole due to grease blockage. All 2,000 gallons of the spill were discharged into a nearby storm drain. The blockage was cleared; the affected area was cleaned up, and disinfected by City of Orange staff.
5/12/03	5/12/03	35884	City of Orange	Hart Park @ National Guard Armory, Orange, Orange County	SSO	1,600	An estimated 1,600 gallons of sewage overflowed from a manhole due to grease blockage. All 1,600 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was cleared; the affected area was cleaned up, and disinfected by City of Orange staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/16/03	5/12/03	35749	City of La Habra	Beach Blvd @ Lambert Road, La Habra, Orange County	SSO	2,000	An estimated 2,000 gallons of sewage overflowed from a manhole due to grease blockage. 500 gallons of the spill were contained, recovered, and returned to the operational sewer system. 1,500 gallons of the spill were not recovered and discharged into a local storm drain and flowed to Coyote Creek. The blockage was cleared; the affected area was cleaned up, and disinfected by City of La Habra staff.
5/17/03	5/17/03	35885	Rancho Cucamonga Water District	5690 Crestline, Cucamonga, San Bernardino County	SSO	1,800	An estimated 1,800 gallons of sewage overflowed from a manhole due to a grease blockage. 800 gallons of the spill were contained, recovered, and returned to the operational sewer system. 1000 gallons of the spill were not recovered and discharged into a local storm drain and to the storm channel where it percolated. The blockage was removed; the affected area was cleaned up, and disinfected by RCWD staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/17/03	5/17/03	35886	City of Yorba Linda	W.Kellogg Drive @ Club View Street, Yorba Linda, Orange County	SSO	5,375	An estimated 5,375 gallons of sewage overflowed from a manhole due to tree root blockage. 1,200 gallons of the spill were contained, recovered, and returned to the operational sewer system. 4,175 gallons of the spill were not recovered and discharged into a local storm drain which flowed to Atwood channel where it percolated. The blockage was removed; the affected area was cleaned up, and disinfected by YLWD staff.
5/20/03	5/20/03	35783	EMWD	29285 Valley Blvd., Sun City, Riverside County	TRW	540,000	An estimated 540,000 gallons of tertiary recycled water (TRW) was released from a ruptured pipe line. All 540,000 gallons of the spill discharged into a local storm drain and flowed through the storm drain into Salt Creek where it percolated. The pipeline was repaired and the street was washed with potable water by EMWD.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/20/03	5/20/03	35889	Special Districts Department	Glen Helen WWTP, San Bernardino, San Bernardino County	SSO	45,000	An estimated 45,000 gallons of sewage overflowed from Glen Helen's headworks due to grease blockage. All 45,000 gallons of the spill were contained in a storage pond at the facility where it percolated. The blockage was removed, the affected area was cleaned up, and disinfected by special districts department staff.
5/22/03	5/22/03	35883	City of Orange	Intersection of Poplar & Orange Wood Avenue	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to grease blockage. 250 gallons of the spill were contained, recovered, and returned to the operational sewer system. 250 gallons of the spill were not recovered and discharged into a local storm drain. The blockage was removed, the affected area was cleaned up, and disinfected by the City of Orange staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/24/03	5/24/03	35843	City of Yorba Linda	5594 Kellog Drive, Yorba Linda, Orange County	SSO	4,500	An estimated 4,500 gallons of sewage overflowed from a manhole due to tree root blockage. All 4,500 gallons discharged into a local storm drain and flowed to Atwood storm channel where it percolated. The blockage was removed, the affected area was cleaned up, and disinfected by Yorba Linda staff.
5/26/03	5/26/03	35763	Private Property Owner	21851 Newland Space#2, Huntington Beach, Orange County	SSO	960	An estimated 960 gallons of sewage overflowed from a manhole due to a private pump station failure. None of the spill was contained and it discharged into a local storm drain and flowed to Talbert Marsh and to the Pacific Ocean. The blockage was cleared, the affected area was cleaned up, and disinfected by a private contractor with the assistance of Huntington Beach city staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notification No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
5/28/03	5/28/03	35887	City of Ontario	3100 Block of East Riverside Drive, Ontario, San Bernardino County	SSO	12,000	An estimated 12,000 gallons of sewage overflowed from a manhole due to Turner lift station failure. A fire in the motor control center (MCC) was caused by gasoline present in the sewer and that gasoline vapor got into the MCC and was ignited by a motor starter. The fire was extinguished and 80% of the spill was contained, recovered, and returned to the operational sewer system. The rest of the spill percolated into the golf course ground. New control panel and pumps were installed; some soil and turf were removed and replaced by new ones. All affected area was cleaned up and disinfected by the City of Ontario staff.